



TILLMAN®

1328 | Premium Top Grain Goatskin TIG Welding Glove

SPECIFICATION SHEET

Description

The Tillman 1328 TIG gloves offer are great for TIG welding and plasma cutting applications.

Made with premium Goatskin these TIG gloves are thin, provide abrasion and flame resistance.

The 1328 gloves are sewn with DuPont Kevlar thread to protect the structural integrity of the seams and have a straight thumb for optimal gripping power and friction resistance when working and holding a TIG torch.

Features

- Premium Top grain pearl Goatskin.
- 4" cuff for added protection.
- Winged thumb Includes Lock stitching with DuPont™ Kevlar® thread for added strength.
- Sizes: S, M, L, XL



Technical Specifications

Glove Material:	Premium, Goatskin
Cuff Material:	Split Cowhide
Lining:	Unlined
Stitching:	DuPont™ Kevlar®
Closure:	Straight cuff

Applications

- Construction sites
- Wind energy
- Utility crews
- Fabrication
- Steel Mills
- Oil & Gas
- Oil pipelines
- Demolition & salvage
- Shipyards
- Manufacturing

Packaging Information

		Piece Information					Inner Pack Info - 6 Pcs					Master Pack Info - 72 Pcs				
Size	SKU	Piece UPC	L	W	H	Wt	Inner Pk UPC	L	W	H	Wt	Master Pk UPC	L	W	H	Wt
Small	1328S	608134132828	11.75	5.50	0.50		NA	11.75	5.50	4.00	1.50	NA	16	12	14	18.00
Medium	1328M	608134132811	12.00	6.00	0.50		NA	12.00	6.00	4.00	1.50	NA	16	12	14	18.00
Large	1328L	608134132804	12.50	6.50	0.50		NA	12.50	6.50	4.00	1.60	NA	16	12	14	19.20
X Large	1328XL	608134132842	13.00	7.00	0.50		NA	13.00	7.00	4.00	1.70	NA	16	12	14	20.40



Prop 65 Warning: This product can expose you to chemicals Hexavalent Chromium (Chromium 6), which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.p65warnings.ca.gov

DuPont™, Nomex® and Kevlar® are trademarks or registered trademarks of E.I. du Pont de Nemours and Company.

John Tillman Co., Compton, CA 90220 • P: (800) 255-513280 • F: (310) 764-0104 • jtillman.com • info@jtillman.com



TILLMAN®

Warning — Gloves are cut-resistant, not cut proof. Extreme caution should be used when handling sharp objects and around machinery. Read, understand and follow all labels and instructions prior to use. Inspect gloves before each use and remove from service if there is any evidence of damage or excessive wear.