

WELDING GLOVES

Glove 101

- ▶ Select gloves made of materials that will perform best according to the specific application.
- ▶ Make sure the glove fits for added safety, comfort, and dexterity. A glove that is too big or small can decrease performance and increase the risk of injury.
- ▶ Engage workers in the selection process – they'll be more likely to wear them if they choose them.
- ▶ Conduct regular inspections to make sure the gloves are in good condition before wearing. Replace any gloves that are worn or torn.

How to Get the Proper Fit

Measure Around Your Dominant Hand



Size:	Inch:
XS	6 - 7
S	7 - 8
M	8 - 9
L	9 - 10
XL	10 - 11
XXL	11 - 12



Welding Safety & Health

HAND & BODY

WELDING GLOVES

Performance Gloves Size & Part Number Chart

	XS	SM	M	L	XL	2XL
Heavy-Duty MIG/Stick	–	–	–	263339	263340	269615
MIG/Lined	–	–	263332	263333	263334	269618
TIG	–	263346	263347	263348	263349	–
TIG/Multitask	–	263352	263353	263354	263355	–
Metalworker	–	–	251066	251067	251068	–

Classic Gloves Size & Part Number Chart

	XS	SM	M	L	XL	2XL
Heavy-Duty MIG/Stick	–	–	–	271877	271887	–
MIG (Pigskin)	–	–	–	279875	279876	–
MIG (Cowhide)	–	–	–	271890	271891	–
TIG	–	–	279897	279898	279899	–
Work	–	–	266041	266042	266043	–